





Change/turn the plunger for correct compression.

[See table below]



<i>Yellow mark</i>	<i>No mark</i>
EX59XL	EX59-39/79
EX59XLET	EX59HENT
EX59XLETI	EX59NTPLUS
EX59XLHE	EX59WSNI
EX59XLNTPLUS	EX59WSNTPLUS
EX59XLWSNI	EX6
EX59XLWSNTPLUS	EX6-49/83
EX59-3979-IECM	EX6-51/83
EX59-3979-IECF	EX6-51/83GREEN
EX6XL	EX6-51WSNT
EX6XL-G	EX651WSNTPLUS
EX6XL-NITIN	EX6NTPLUS
EX6XLET	EX6PE
EX6XLNTPLUS	EX6PEPLUS
EX6XLPLUS	EX6PEWS
EX6XLSKPLUS	EX6PEWSPLUS
EX6XLWS	EX6WS
EX6XLWSNI	EX6WSNI
EX6XLWSNTPLUS	EX6WSNTPLUS
EX6XLWSPLUS	MC-5
EX651XLNT	MC-7
EX651XLWSNTPLUS	MC-9
EX6-4983-IECM	
EX6-4983-IECF	
EX6-5183-IECM	
EX6-5183-IECF	